

SERVICE INFORMATION

Model: PMD-661/U1B
PMD-661/N1B
PMD-661/F1B

Ref.No.: Pro09-F012

Date: 20 April 2009

Importance: A
(Implementation to all repair units recommended)

Subject: Microcomputer firmware Update -Ver. A-1.14-

1. SUBJECT:

Microcomputer firmware update (Ver. A-1.10 -> A-1.14)

2. SYMPTOM:

1. While opening door and pushing power switch long term, sometimes "MPGLANG1" is created.
2. The unit can not STOP, while pushing "STOP" button at "Executing" is displayed.
3. Flashing time of " " is not correct when capacitor of Battery is low.
4. The customer can set "REC Timer" and "Play Timer" at same time.
5. Sound is interrupted at continuous playback that is made by "manual Track".
6. While recording signal at Digital IN, "Err D.IN" is indicated moment.
7. Same kind of sound (about 1 second) is repeated at "Seek" function of "Audible Search".
8. "Store" is indicated when "Timer Play/Timer Record" is not set
9. Audio file is not divided, then "Play Reserved" is indicated.
10. Push the "ENTER" button at the display of "RENAME" without changing, "Already Exists" is indicated.
11. White noise is occurred from speaker while pushing "STOP", "PLAY-PAUSE" and "PLAY-STOP",
12. While adjusting the "Rec Level" at Rec Pause, indication is changed from "Err Card 9" to "Err Card 10"
13. While starting the unit with SD card of "Kingston 4GB", "Err Card 1" is indicated when pushing the "REC" button.
14. Additional of "Logo On/Off" function at No.6 in Service Menu.

3. MODELS AND SERIAL NUMBERS TO WHICH THE ABOVE MODIFICATION IS APPLIED IN THE MARKET:

Please apply the above modification to the production models in the following serial numbers.

(Last 5-digit)

Model	Serial Number
PMD-661/U1B	~ 2000091400xxxx
PMD-661/N1B	~ 2000091600xxxx