

SERVICE INFORMATION

Model: PMD620/U1B
PMD620/N1B

Ref.No.: Pro09-F013

Date: 23 April 2009

Importance: A
(Implementation to all repair units recommended)

Subject: Microcomputer firmware Update -Ver. A-2.33-

1. SUBJECT:

Microcomputer firmware update (Ver. A-2.27- > A-2.33-)

2. SYMPTOM:

1. The time counter indicated error at "Audio Search" on MP3 files (24 hours)
2. While searching 4GB file at Audible Search Seek, unit goes back to the beginning of track.
3. Noise is occurred, while changing the file from 24 bit to 16 bit at "Audible Search Seek".
4. The unit did not understand size of characters while renaming.
5. Name of long file did not scroll while changing the function from "STOP" to "Play Stop" by ">>" button.
6. While playing the no music files, "Err Format 1" is indicated once a twice.
7. The unit indicated wrong Bit Rates or wrong FS at picture of information.
8. While recording the 999-file, file size arrives at 4GB, then unit stops recording, but picture is still indicated at "REC" mode.
9. While starting the unit with SD card of "Kingston 4GB", "Err Card 1" is indicated when pushing the "REC" button.

3. MODELS AND SERIAL NUMBERS TO WHICH THE ABOVE MODIFICATION IS APPLIED IN THE MARKET:

Please apply the above modification to the production models in the following serial numbers.

Model	Serial Number
PMD620U1B	~ 2000091800xxxx
PMD620N1B	~ 2000091800xxxx